

AMENDMENTS TO THE DRAWINGS

The drawings were objected to as failing to comply with 37 CFR 1.84(p)(5) because they include the following reference sign(s) not mentioned in the description: 30, 68, 230. Applicants submit a set of corrected drawings, which accompany this amendment, removing the reference numerals not mentioned in the specification, namely reference numerals 30, 68 and 230. While reference numerals 30, 68 and 230 were removed from Figures 1, 2, 3 and 4 only, Applicants have also submitted replacements sheets including those figures that were not amended.

Attachment: Replacement sheets of drawings.

Application No.: 09/977,543


Docket No.: 65857-0033

REPLACEMENT SHEET

Inventor: Matthew M. Persohn

Title: COUPLING ASSEMBLY WITH ROTATION LOCK

Attorney Docket No.: 65857-0033






FIG 1A




FIG 1B




FIG 1C








FIG 3A




FIG 4





FIG 8




FIG 5



FIG 6





FIG 7




FIG 9



FIG 10






FIG 12

